


SERVICE BULLETIN No. 156

FENNER FLUID POWER Motor (Part # 15727) Drain Plugs Removal

Fenner Fluid Power recommends removal of the plastic plugs from the motor end cover and motor housing as per illustration. Removal of these plastic plugs will prevent water/oil to collect within the motor housing. Removal of these plugs will also alert you to an oil leak, should a Pump Shaft Seal or Nylite washer fail beneath the motor.



Meyer Products assumes no responsibility for installations not made in accordance with these instructions.